

CONSTRUCTION REPORT

Site Diary and Safety Walk

Land walk with a buyer's representative

SITE

Land plot, Katampe Extension
Abuja, FCT

PREPARED FOR

Not stated

INSPECTED BY

Test Founder

SIGNED BY

Walknote evaluation team
Reviewed for this case study

REFERENCE

None

TEMPLATE

Site Diary and Safety Walk
Version 1



A5W3-FULH

Scan the code or open <http://localhost:3610/verify/A5W3-FULH> to check that this report is the one that was signed.

Made with Walknote

Summary

What the inspector recorded on this visit, counted.

0

MISSING

0

PRESENT

0

NOT INSPECTED

0

COULD NOT REACH

6

NOTED

10 photos (5 with no note recorded) · 1 voice clip · 20 template items marked Not recorded

Contents

Plot	3 · 6 items, 10 photos
Not recorded	5
Sign-off	7
Limitations	7
Check this report	8
Appendix: how this report was made	9



Noted +0:06	representative of my client Visitors to the site The representative of the client was observed over there trying to take a view of the property. Where: over there THE INSPECTOR SAID "You can see the representative of my client over there, trying to take a view of the property"
Noted +0:45	topography Ground and access conditions The plot appears to look hollow, but it is just the topography of the property. THE INSPECTOR SAID "this place looks like it is hollow, but it's just the topography of the property" Photo 14
Noted +0:50	retaining wall Work carried out, by area The inspector noted that this retaining wall was done here. Where: here THE INSPECTOR SAID "As you can see, we did this retaining wall here" Photo 15
Noted +0:54	retaining wall Work carried out, by area The retaining wall spans all through that place and to the right-hand side to that place also. Where: all through that place, right? And to your right-hand side, you can see it to that place also THE INSPECTOR SAID "This retaining wall spans all through that place, right? And to your right-hand side, you can see it to that place also" Photo 16
Noted +1:02	container Site office outside the structure, with toilets and material storage The container on site was noted. Where: on site THE INSPECTOR SAID "This is our container on site" Photos 17, 18
Noted +1:06	retaining wall Work carried out, by area This retaining wall was finished a little over a week ago. THE INSPECTOR SAID "This is the retaining wall we just finished uh a little over a week ago"



Photos




Photo 9 · 0:30 into the visit
No note recorded



Photo 10 · 0:34 into the visit
No note recorded



Photo 11 · 0:38 into the visit
No note recorded



Photo 12 · 0:42 into the visit
No note recorded



Photo 14 · 0:48 into the visit
topography



Photo 15 · 0:52 into the visit
retaining wall



Check this report
A5W3-FULH · version 1
<http://localhost:3610/verify/A5W3-FULH>

Walknote evaluation
Made with Walknote




Photo 16 · 0:56 into the visit
retaining wall



Photo 17 · 1:00 into the visit
container



Photo 18 · 1:04 into the visit
container



Photo 19 · 1:08 into the visit
No note recorded

Not recorded

Items on the template that the inspector did not mention. They are listed as Not recorded. They are not read as satisfactory.

Conditions and working hours	Weather today	Not recorded
Conditions and working hours	Working hours	Not recorded
Labour and plant	Labour on site by trade	Not recorded
Labour and plant	Subcontractors on site	Not recorded
Labour and plant	Plant and equipment on site	Not recorded
Materials and deliveries	Materials delivered today	Not recorded
Materials and deliveries	Materials stored on site	Not recorded
Work done	Work stopped or not started	Not recorded
Instructions, visitors and delays	Instructions received or given	Not recorded



Check this report
A5W3-FULH · version 1
<http://localhost:3610/verify/A5W3-FULH>

Walknote evaluation
Made with Walknote

Page 5 of 9

Instructions, visitors and delays	Delays and their cause	Not recorded
Instructions, visitors and delays	Accidents or near misses reported	Not recorded
Instructions, visitors and delays	Photos taken for the record	Not recorded
Site safety walk	Project site board shows the required details	Not recorded
Site safety walk	Register of workers and visitors	Not recorded
Site safety walk	Skip or bin for waste	Not recorded
Site safety walk	Protective equipment worn	Not recorded
Site safety walk	Nobody living on site	Not recorded
Site safety walk	Fence or hoarding where work is close to the street	Not recorded
Site safety walk	Fire extinguishers valid and not expired	Not recorded
Site safety walk	Hazard record book kept	Not recorded



Sign-off

Filled in by people only. Walknote AI never fills the name, number, seal, signature or date.

NAME OF SIGNATORY

Walknote evaluation team

POSITION

Reviewed for this case study

REGISTRATION NUMBER (FOR EXAMPLE COREN)

SEAL

SITE LOG BOOK SIGNATURE

COUNTERSIGNATURE OF THE AGENCY INSPECTOR

SIGNATURE

DATE

Limitations

This diary was written from what the inspector said and photographed on the day. A row nobody mentioned reads Not recorded. Walknote counts nothing itself: head counts, quantities and hours are as the inspector said them. The log book signature is a person's, never filled in by Walknote AI.

This report records what the inspector said and photographed on the visit. Items marked Not recorded were not mentioned. It is a record of a visit, not a guarantee about anything that was not seen or said.

No notes or photos were recorded for: Materials and plant yard, Site entrance and board, Site office, Street side and perimeter, Work areas.

This template follows: Lagos State Building Control Agency Regulations 2019: Schedule 11 (site log book) and Regulations 6, 8(3) and 14 (Lagos State Building Control Agency (LASBCA)); Standard Bidding Document, Procurement of Large Works: clause 53 (claims and contemporary records) (Lagos State Public Procurement Agency).



Check this report
A5W3-FULH · version 1
<http://localhost:3610/verify/A5W3-FULH>

Walknote evaluation
Made with Walknote

Page 7 of 9

Check this report



REPORT ID

A5W3-FULH

Open <http://localhost:3610/verify/A5W3-FULH> or scan the code to check that this is the report that was signed. This report is tamper-evident: a copy that was edited, re-saved or compressed will not match. The check page names the version and says if a newer one replaced it.

VERSION

1

CONTENT FINGERPRINT (SHA-256)

0936dcc6ed46b2a018577ddf07d99c0217ec8a7ea6f75d4e1637a2d5523513c6

SIGNING KEY

ed25519:c9cf074c8e92d49b

The fingerprint of this PDF file is shown on the check page, because a file cannot print its own fingerprint.

Made with Walknote



Check this report
A5W3-FULH · version 1
<http://localhost:3610/verify/A5W3-FULH>

Walknote evaluation
Made with Walknote

Page 8 of 9

Appendix: how this report was made

Walknote AI

Walknote AI turned the inspector's voice notes into a transcript, picked out each statement with the exact words used, and drafted these sentences from those statements only. Each sentence was checked against the statements it cites by fixed rules and by a second, separate check. Photos were attached as evidence and never used to add a finding. The inspector reviewed the report, edited what needed editing and approved it. The signature, registration number and seal are filled in by people only.

6 drafted sentences, 0 edited by the inspector · 6 recorded statements.

Photo index

NO.	TIME	AREA	SHA-256 OF THE ORIGINAL
9	0:30	Plot	fd1f0c19a2395423a8b2e7516f4bdf278f5bd494d8438ca95dd0e6400c94d829
10	0:34	Plot	731958b06124ada50b97be7a28ae86c19d6b29b530479b992effea7d107839b3
11	0:38	Plot	f336ba6535ad1da8d0d776f9f47082cfa60a629955934efc5d9e27d96d087a62
12	0:42	Plot	cbdcf663ca66854ef845ea5ebf995b7b82568ec8e5f1135b98af44a06a6941a3
14	0:48	Plot	e12cc3542b332f03925e371787c6a9311c6bd932d244fdceccb48380f739af8d
15	0:52	Plot	e15475fbd2de6c02ba5e4ea0f482eddd5a4b8763509e7571b48fa26d91ce3104
16	0:56	Plot	96c51df0f1bad362300a2d94d03de4ce2d1c9de023762040426376678ba1202a
17	1:00	Plot	21d37d8444fd9d486d243e2f45060b9a6d46e8ffa64613d736d317681bdd47a2
18	1:04	Plot	bd59b33de39ec796455217cbaa39872c23166e9e584529f3a325f7798316d645
19	1:08	Plot	e5f6ef3390246849c41648ab69cd7cb625d8b64a1177168e2d48b63cb1451665

Voice clips

CLIP	SHA-256 OF THE ORIGINAL
2893d2a2	44d6599033cadf953ca4d3a3a0a8ce0836b3d274aae737e2c70651d1e6067079

Signed manifest

Visit	5378c9a1d9ae4929a94683b52a278c09
Version	1
Template	site-diary-safety-walk
Originals listed	26
Signing key	ed25519:c9cf074c8e92d49b
Ed25519 signature	Gg090BrJvMAK1C00AzBh446Mv/6qezPMjP2dr+iqL+dQ61sN7j86WKCRbFat4JDZ8xNwF6pj6TcFg1RL3+IDA=

The manifest lists the fingerprint of the content and of every original photo and voice clip. It is signed with the Walknote key shown.



Check this report
A5W3-FULH · version 1
<http://localhost:3610/verify/A5W3-FULH>

Walknote evaluation
Made with Walknote

Page 9 of 9